

Code E5

Situation: Incorrect heating and filtering, buzzer warning.

Cause: The water temperature in the pump exceeds 47°C (117°F).

Reason 1: The water inlet or outlet on the inner wall are blocked.

Solution 1: Clean the water inlet and outlet. Then reset the temperature control sensor.



Reason 2: The hose connecting the inside and outside of the Liner is not straightened, or the hose is flattened, which reduces the water flow speed.

Solution 2: Pump the Liner with enough air again, which will straighten the hose connecting the inside and outside of the Liner. If it fails, replace a new liner.

Then reset the temperature control sensor.



Tips:

Press the button to reset the temperature control sensor.

